

City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 1 of 1

Sewershed: Gwynns Falls

Company: Savin

Date: 7/30/2009

Test to be performed:

Smoke ☐ Dyed Water ☒

Ground Condition:

Dry ☒ Damp ☐ Wet ☐

Supervisor: JAW

Manhole_ID: S01WW_005MH

Test ID: D1032-025006

Notification Made: NA

(Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Water Level	
0			Manhole	S01WW_019MH
107.8000031			Dye Test Visible	@ TBI - downspout
108.1999969			Dye Test Visible	@ TBI - toilet
110.3000031	10		Tap Break-in Intruding	From 4117 Kathland
111			Manhole	S01WW_005MH
111			End of Survey	